

FIG. 3





FIG. 4



T2/T1 = DUTY CYCLE

FIG. 5




FIG. 6A




FIG 6B







FIG. 6C







МОДЕ	M1′	M2	N/3	M4	NS.
STEP UP	NO	OFF	NO ON	OFF	OFF
STEP DOWN	OFF.	PWM ON	£10	£10	OFF.
ENERGY RECEIVE	OFF.	OFF.	OFF	NO	NO
DATA RECEIVE	OFF.	OFF	0FF	NO	NO
DATA XMIT	NO	OFF	MODULA TION ON	NO	NO

FIG. 8